

Firmware & Changelog (Multi Temperature V2)



How do I update the firmware?

Please refer to [Updating Firmware](#) on the page about our Lobar Maintenance Tool.

Firmware Update Downloads

Download:	app-nrf9160-temperature-TZ2-0.2.19+battery-mcuboot-slot0-boot.hex	current version
	app-nrf9160-temperature-TZ2-0.1.3-mcuboot-slot0-boot.hex	last version without NB-IoT support

Changelog

app-nrf9160-temperature

This changelog's format is based on [Keep a Changelog](#), and this project adheres to [Semantic Versioning](#).

0.2.19 - 2022-12-15

Fixed

- RF Switch behavior on LTE join

0.2.18 - 2022-12-14

Fixed

- Confirmation of remote config and firmware updates added

0.2.17 - 2022-12-07

Fixed

- RF Path selection now as expected

0.2.16 - 2022-10-07

Added

- Status Packet now contains Modem Information including battery voltage and temperature

Changed

- Status Packet set to daily at 0h with random minute and second

0.2.15 - 2022-09-26

Optimized

- Now using High Precision Clock for Onewire Communication

Added

- Startup Tests

- Firmware Update Downloads
- Changelog
 - 0.2.19 - 2022-12-15
 - Fixed
 - 0.2.18 - 2022-12-14
 - Fixed
 - 0.2.17 - 2022-12-07
 - Fixed
 - 0.2.16 - 2022-10-07
 - Added
 - Changed
 - 0.2.15 - 2022-09-26
 - Optimized
 - Added
 - 0.2.14 - 2022-08-01
 - Fixed
 - 0.2.13 - 2022-08-01
 - Fixed
 - Optimized
 - Added
 - Changed
 - 0.2.0 - 2022-03-22
 - Added
 - 0.1.3 - 2022-02-18
 - Fixed
 - 0.1.2 - 2022-01-31
 - Fixed
 - 0.1.1 - 2022-01-31
 - Changed
 - 0.1.0 - 2022-01-28
 - Added
 - Changed
- Firmware Update Downloads
- Changelog
 - 0.1.3 - 2022-02-18
 - Fixed
 - 0.1.2 - 2022-01-31
 - Fixed
 - 0.1.1 - 2022-01-31
 - Changed
 - 0.1.0 - 2022-01-28
 - Added
 - Changed

0.2.14 - 2022-08-01

Fixed

- Added missing call to adopt temp config in lorawan

0.2.13 - 2022-08-01

Fixed

- NbTrans behaviour
- a case that added an invalid packet to the queue
- a bug leading to system restart when trying to send while all channels are blocked

Optimized

- optimized onewire Timings
- settings for long cables

Added

- A packet containing just a 0 if no sensor was found ## 0.2.1 - 2022-03-22

Changed

- order of config parameters

0.2.0 - 2022-03-22

Added

- nbiot upload
- reboot on lost LoRaWAN connection

0.1.3 - 2022-02-18

Fixed

- Increase power on delay after sleep, so sensors have enough time to convert temperature.

0.1.2 - 2202-01-31

Fixed

- Fix reading of testing firmware name (fixes self test factory).

0.1.1 - 2022-01-31

Changed

- Revert status message to original port 1 format for backwards compatibility.
- Add Power-On wait between activating sensor power and reading sensor data.

0.1.0 - 2022-01-28

Added

- New firmware created from app-lorawan-onewire-bridge and app-nrf9160-onewire-bridge.
- LoRaWAN upload only (so far).
- Add RemoteConfiguration, TimeSync, and LostReboot feature.

Changed

- Internal Sensor is now an emulated Sensor with all zero ID that holds the temperature measured inside the nrf. Temperature resolution is down to 1°C. Changes should be compatible with LoRaWAN format used by LoRaWAN-only 1-wire bridge.
- Change status message to new Lobar Unified Status Telegram format (on port 64).



How do I update the firmware?

Please refer to [Updating Firmware](#) on the page about our Lobar Maintenance Tool.

Firmware Update Downloads

Download:	app-nrf9160-temperature-TZ2-0.1.3-mcuboot-slot0-boot.hex	current version
-----------	--	-----------------

Changelog

app-nrf9160-temperature

This changelog's format is based on [Keep a Changelog](#), and this project adheres to [Semantic Versioning](#).

0.1.3 - 2022-02-18

Fixed

- Increase power on delay after sleep, so sensors have enough time to convert temperature.

0.1.2 - 2022-01-31

Fixed

- Fix reading of testing firmware name (fixes self test factory).

0.1.1 - 2022-01-31

Changed

- Revert status message to original port 1 format for backwards compatibility.
- Add Power-On wait between activating sensor power and reading sensor data.

0.1.0 - 2022-01-28

Added

- New firmware created from app-lorawan-onewire-bridge and app-nrf9160-onewire-bridge.
- LoRaWAN upload only (so far).
- Add RemoteConfiguration, TimeSync, and LostReboot feature.

Changed

- Internal Sensor is now an emulated Sensor with all zero ID that holds the temperature measured inside the nrf. Temperature resolution is down to 1°C. Changes should be compatible with LoRaWAN format used by LoRaWAN-only 1-wire bridge.
- Change status message to new Lobar Unified Status Telegram format (on port 64).

- [Firmware Update Downloads](#)
- [Changelog](#)

- [0.2.19 - 2022-12-15](#)
 - [Fixed](#)
- [0.2.18 - 2022-12-14](#)
 - [Fixed](#)
- [0.2.17 - 2022-12-07](#)
 - [Fixed](#)
- [0.2.16 - 2022-10-07](#)
 - [Added](#)
 - [Changed](#)
- [0.2.15 - 2022-09-26](#)
 - [Optimized](#)
 - [Added](#)
- [0.2.14 - 2022-08-01](#)
 - [Fixed](#)
- [0.2.13 - 2022-08-01](#)
 - [Fixed](#)
 - [Optimized](#)
 - [Added](#)
 - [Changed](#)
- [0.2.0 - 2022-03-22](#)
 - [Added](#)
- [0.1.3 - 2022-02-18](#)
 - [Fixed](#)
- [0.1.2 - 2022-01-31](#)
 - [Fixed](#)
- [0.1.1 - 2022-01-31](#)
 - [Changed](#)
- [0.1.0 - 2022-01-28](#)
 - [Added](#)
 - [Changed](#)

- [Firmware Update Downloads](#)
- [Changelog](#)

- [0.1.3 - 2022-02-18](#)
 - [Fixed](#)
- [0.1.2 - 2022-01-31](#)
 - [Fixed](#)
- [0.1.1 - 2022-01-31](#)
 - [Changed](#)
- [0.1.0 - 2022-01-28](#)
 - [Added](#)
 - [Changed](#)